



प्रमाणपत्र

प्रमाणित करण्यांत येते की, Ramsheth Thakur Public School Kharghar Plot No. 11,11A, Sector-19 Kharghar, Navi Mumbai या शाळेच्या इमारतीची दिनांक १८/०७/२०१९ रोजी प्रत्यक्ष पहाणी केली असून सदर इमारत नॅशनल बिल्डींग कोड २००५ च्या भाग ४ मधील मार्गदर्शक तत्वानुसार बांधलेली असून सदर इमारत पहाणी केली त्या दिवशीच्या स्थितीवरून ती संरचामक दृष्ट्या सुरक्षित व स्थिर आहे.



कार्यकारी अभियंता
सा.बां. विभाग पनवेल



सहाय्यक अभियंता श्रेणी-१
सा.बां.उपविभाग, क्र.१ पनवेल

जा.क्र./साबांवि/पनवेल/रेशा/ ९५१९
कार्यकारी अभियंता यांचे कार्यालय
सा.बां. विभाग पनवेल
दिनांक २४-१०-२०१९

Translation

CERTIFICATE

It is certified that the school building of Ramsheth Thakur Public School, Kharghar, Plot No. 11 & 11A, Sector-19, Navi Mumbai has been inspected on 18th July 2019. On observation it is found that the building is built in accordance to National Building Code 2005, Part 4 and on inspection the building structure was found to be safe and stable.

-Sig-

Executive Engineer
P.W. Department, Panvel

-Sig-

Asst. Engineer Grade-I
P.W. Sub Division, No.1, Panvel

Outward No/PWD/Panvel/Resha/4519
Office of Executive Engineer
P.W. Department, Panvel
Date:24/07/2019



ATTESTED BY ME

KAVITA RAJENDRA AGRAWAL
ADVOCATE & NOTARY
Office No. 7, Harave Hara Mall,
Sector - 13, Kharghar
Navi Mumbai- 410 210
Mob : 8898978099 / 9890055818

26 JUL 2019